

## Roll Up Roll Up

Activity	Mobile Climbing Wall
----------	----------------------

Hazard	Frequency	Probability	Severity	Final Score	Controls
Risk of fall from height	2	1	5	10	Use of approved climbing equipment and correctly trained supervision present at all times.
Harness failure	2	1	5	10	Use of approved climbing harnesses. Inspected and maintained in accordance with manufacturers instructions.
Karabiner failure	2	1	5	10	Use of self-locking approved karabiners. Inspected and maintained in accordance with manufacturers instructions.
Auto belay failure	2	1	5	10	The auto belay system is a redundant hydraulic system and in an unlikely event of a failure the system would freeze at its last position.
Structural collapse	2	1	5	10	The climbing wall will not be operated in adverse weather conditions or in winds exceeding 30 mph. In storm conditions the wall is lowered to the ground.
Risk from equipment mis use	2	1	3	6	All staff to have received training on this equipment

Date of Assessment & sign		
Review 1 & sign	3/3/11	<i>[Signature]</i>
Review 2 & sign		
Review 3 & sign		

Frequency		Probability		Severity	
Frequent	5	Highly Likely	4	Major	4
Regular	4	Possible	1	Serious	3
Seldom	2	Unlikely	0	Minor	1

Score	Action
<13	No further action required
13 - 47	Significant risk - further action required
>47	High risk - immediate action required